



**ZARGES**

**Service Pack SP2 No.: 800429**

Contents of Service Pack 2:

1. 4 bolts
2. 4 rollers

**Removal:**

- Unscrew bolts (1) with a 3mm Allen key.
- Take out rollers (2) from the slide mechanism.

**Installation:**

- Put bolts (1) through the rollers (2).  
Apply some Loctite 2701 thread adhesive on the bolt threads and hand-tighten the slide mechanism threads.  
Wipe off any emerged Loctite 2701. No Loctite 2701 should get between bolts (1) and rollers (2).

**ATTENTION** The slide mechanism may only be used after the thread adhesive Loctite 2701 has dried.

- Finally, check the rollers for ease of movement.

The replacement of the rollers must be noted in the inspection booklet.

